

OUT56762

P 232219Z  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEKDA/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 5516.

1005 SEP 25 22 35Z

24 SEP 1965  
 COPIES RECEIVED

By No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CCD	
	IPD	
	CB	
	DIA-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 23 WAS USED IN MISSION 8045 FLOWN ON 21 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD WHERE NOT DEGRADED BY WEATHER CONDITIONS.

B. 9R SIDE: A NUMBER OF SHORT IRREGULAR PLUS DENSITY STREAKS ARE PRESENT AT RANDOM IN FRAMES 001 TO 240. FRAMES 721 TO 980 CONTAIN A CONTINUOUS IRREGULAR PLUS DENSITY STREAK WITHIN 3.0" OF THE OUTBOARD EDGE. INTERMITTENT LINEAR PLUS DENSITY STREAKS ARE PRESENT ON THE INBOARD EDGE OF FRAMES 873 TO 980. PINHOLES ARE NOTED INTERMITTENTLY THROUGHOUT THE MATERIAL. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 556 AND 1952. FRAME 1031 CONTAINS A BREAKDOWN SPLICE. A HEAVY SCRATCH DEGRADES FRAME 721. FRAME 733 CONTAINS A BLISTER AND EMULSION LIFTS ARE NOTED IN A CORRESPONDING LOCATION IN FRAMES 734 AND 735.

C. 9L SIDE: A MINUS DENSITY STREAK 1.4" FROM THE INBOARD EDGE IS PRESENT ON FRAMES 0001 TO 1041. THE MINUS DENSITY STREAK ENDS

SECRET

-2-

AT THE BREAKDOWN SPLICE WHICH WAS MADE THROUGH THE MANUFACTURER'S SPLICE ON FRAME 1041. HANDLING MARKS AND EMULSION LIFTS ASSOCIATED WITH THE SPLICES ARE ON FRAMES 1041 TO 1043. FOG DUE TO LIGHT LEAKS ARE PRESENT PERPENDICULAR TO THE MAJOR AXIS AND LOCATED ON FRAMES 1, 2, 2147 AND 2149. EMULSION LIFTS ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. SEE FRAMES 950, 1040 AND 1392 AS AN EXAMPLE. MINUS DENSITY COMETS ARE PRESENT ON FRAMES 219 AND 1096. TITLE FLAKING OCCURRED ON EACH EVEN NUMBERED FRAME OF PARTS 2 AND 3 WHICH MADE THE MISSION NUMBER DIFFICULT TO READ AT TIMES.

D. BOTH SIDES: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ON BOTH EDGES THROUGHOUT THE MISSION. THE DATA CHAMBER IS MISSING ON FRAME 1. THE LAST TITLED FRAME OF THE MISSION IS 2149.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING IS GOOD.

C. CLOUDS COVERED APPROXIMATELY 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--